



CITY OF BISHOP

377 West Line Street - Bishop, California 93514
Post Office Box 1236 - Bishop, California 93515
760-873-8458 publicworks@ca-bishop.us
www.ca-bishop.us

Public Works Report

August 2009

Water

1. Bebee Corporation completed the installation of new 8" water main under Grove Street. This work included the following:
 - 3,121 feet of new 8" C900 plastic water main under Grove and Hammond Street.
 - 6 new Mueller fire hydrants
 - 68 new poly water services and meter boxes (no meters were installed)
 - 3 new tie-ins (1. Hammond and West Pine, 2, Hammond and West Elm, 3. Grove and North Warren)
2. Removed older model Pacific States fire hydrant and replaced it with new Mueller hydrant at the intersection of North Warren and Academy.
3. After much work and replacement of parts we have the sodium hypochlorite generator working properly.
4. Performed grounds maintenance at wells 2 and 4.
5. Removed and replaced curb stop valve at the Inyo Register.
6. Took monthly readings of all water meters.
7. Took routine bacteria samples.
8. Continued to work with Eco-Logic on rate study.
9. Retested residential backflow valves that owners have repaired after failing test.
10. Devon, who is the City of Bishop's backflow specialist tested and passed his Backflow renewal test.

Sewer

1. City forces constructed a new manhole at the intersection of Grove and Hammond Streets.
2. Lowered and raised manholes on Grove Street that were effected by pavement overlay.
3. Performed grounds maintenance at the Waste Water Treatment Plant.

4. Made routine inspections of grease interceptors.
5. Generated a No Spill Certification for the State and reported the same.
6. Performed routine main line cleaning in trouble areas.
7. Cleaned grit and sludge drying beds.
8. Performed maintenance and irrigated the 40 acre sewer plant pasture.

Streets

1. Bebee Corporation completed the construction of the Grove Street Sidewalks Project.
2. Constructed new survey monument wells on Grove Street that were affected by the pavement overlay.
3. Trimmed trees that were inhibiting line of sight for various street signs.
4. Repaired and or replaced various street signs.
5. Patched potholes and gutters where needed.
6. Swept city streets and alleys.
7. Provided weed control on city streets and alleys
8. Continued work with consultants on plans and environmental documents for future street projects.

Miscellaneous

1. Made minor repairs and performed maintenance to light trucks and heavy equipment.
2. Replaced flights and flight belts on newer sweeper.
3. Provided weekly safety meetings for public works crew.