



# CITY OF BISHOP

377 West Line Street - Bishop, California 93514  
Post Office Box 1236 - Bishop, California 93515  
760-873-8458 publicworks@cityofbishop.com  
www.cityofbishop.com

## Public Works Report

July 2015

### Water

1. SCADA system sustained damage to electrical components during electrical storm. Public Works Staff operated system manually for the majority of the month.
2. As a result of the electrical storm pressure transducers at both tanks and the Cla-Val transducer were replaced.
3. Investigated a complaint of low water pressure at 263 South Second Street. Found the problem to be plugged up faucet screens. Assisted the customer with cleaning of screens and remedied the issue.
4. Repaired a fire hydrant in the Vons parking lot. Hydrant was hit by a vehicle.
5. Poured a fire hydrant valve box surround on South Warren Street.
6. Adjusted valve box and poured surround on service at the Elms Motel.
7. Continued annual testing of all back flow valves within the city.
8. Continued annual main line valve exercising.
9. Continue working with Terra Verde to implement solar power at Wells 2 and 4.
10. Performed grounds maintenance at Wells 2 and 4 as well as the tank site.
11. Took monthly readings of all water meters.
12. Took routine bacteria samples.

### Sewer

1. Cleared tules from pond sample sites.
2. Sampled plant influent and ponds for Total Nitrogen.
3. Provided daily monitoring and made minor modifications to the Pilot Project.
4. Performed grounds maintenance at the Waste Water Treatment Plant.
5. Continued with the Collaboration effort with Eastern Sierra Community Services District.

6. Cleaned sludge drying beds.
7. Made routine inspections of grease interceptors.
8. Performed routine main line cleaning in trouble areas.

### **Streets**

1. V&C Construction installed the final two street lights on South Warren Street. This work completed the project.
2. Continued installing miscellaneous street signs along the Warren Street Project.
3. Constructed cross gutters at intersection of Central and East Elm, and at the intersection of Howard and East Elm Streets.
4. Removed large root and patched the pavement in the alley between Willow and May Street in the 330 block.
5. Cleaned weeds and debris to enhance drainage at the east end of Clarke Street.
6. Repaired and or replaced bent fence posts in the parking lot at the north end of Whitney Alley.
7. Participated in Inyo Local Transportation Commission meeting.

### **Miscellaneous**

1. Removed several damaged sidewalk panels in the Park and replaced them.
2. Attended California Joint Powers Authority training. The trainings covered Hearing Conservation / Heat Stress.
3. Performed maintenance and serviced Public Works vehicles and equipment.
4. Provided weekly tail gate safety for the Public Works crew.
5. Hauled trash and debris from Fowler Pit to the Sunland Landfill.